DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-000706 Address: 333 Burma Road **Date Inspected:** 23-Oct-2007

City: Oakland, CA 94607

OSM Arrival Time: 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes No n/a **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No **Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component:** Angle and Slot Beam

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector Sherri Brannon arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China to periodically monitor welding and Quality Control (QC) functions. While on site the QA Inspector observed and/or discovered the following.

Quality Assurance (QA) Inspector, Sherri Brannon worked on setting up notebooks and filing submittal's, state letter's of approval and welding quality control plan addendums (WQCP). Also, worked on updating spreadsheets and creating tracking logs for tracking various QA, Office of Structural Materials (OSM) functions.


Inspection of Shape Material:

Quality Assurance (QA) Inspector Brannon received shape (angle and slot) material list for the 89 Meter mock-up received from American Bridge/Fluor (ABF). QA Inspector Brannon went to the ZPMC material storage yard accompanied by ZPMC Quality Assurance Mr. Tao Lei. QA Inspector Brannon performed visual verification of a total of 5 shapes for 89 Meter mock-up. The shapes were observed for their identification tags, general condition and markings. Shape material thicknesses range from 8mm to 14mm. The shapes were designate Grade Q235B. Shape material list for 89 Meter mock-up was accompanied with material test reports (MTR's) RFI ABF-RFI-000556R00: subject: Rolled Shapes substitution for mock-ups.

NOTE:QA Inspector Brannon did not assign a lot number to the shapes due to when identifying the material was missing traceability identification markings for the angle and slot (channel)shapes. QA Inspector Brannon informed Task Leader Robert Cuellar and Task Leader Dave McClary of QA Inspector Brannon's findings. This discrepancy was discussed by Caltrans/ABF and ZPMC during todays issues meeting and it was agreed that such material could be used on the Tower Mock-Ups only and not for production.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

No relevant conversations on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Brannon,Sherri	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer